

Message Text

UNCLASSIFIED

PAGE 01 CANBER 01881 290932Z

53

ACTION FBO-01

INFO OCT-01 EA-07 ISO-00 ABF-01 /010 W

----- 007465

R 290652Z MAR 74

FM AMEMBASSY CANBERRA

TO SECSTATE WASHDC 2885

INFO AMCONGEN MELBOURNE

AMCONGEN SYDNEY

UNCLAS CANBERRA 1881

FOR: A/FBO

E.O. 11652: N/A

TAGS: ABLD, AS

SUBJ: EMERGENCY REPAIRS TO GOVERNMENT-HELD REALTY AT
CONSTITUENT POSTS.

1. PROPERTY 21307 - THE FOLLOWING IS FURNISHED FROM
AMCONGEN, MELBOURNE: "VIOLENT THUNDER STORMS, MARCH 23
AND 24, ACCOMPANIED BY HIGH WINDS AND DELUGE OF RAIN IN AN
HOUR, CAUSED MAJOR DAMAGE TO ROOF AND INTERIOR GOVERNMENT-
OWNED PROPERTY AT 36-38 ANDERSON STREET, MELBOURNE. MANY
ROOF TILES WERE DISPLACED AND BROKEN BY THE HIGH WINDS AND
TREE BRANCHES. ESTIMATES OF IMMEDIATE REPAIRS FOLLOW:

2. "REPAIRS TO ROOF AND PLUMBING: DOLS 600 (USDOL898.82) -
VENDOR ASHWORTH BROTHERS P/L, BRENCHLEY PLACE, PRAHAN.

3. "REDEEMING WATER-DAMAGED WALLS: DOLS 900 (USDOLS1340.79) -
VENDOR H. OLIVER & SON P/L, 434 TOORAK ROAD, MELBOURNE".

4. PROPERTY 41307 - THE FOLLOWING IS FURNISHED FROM
AMCONGEN SYDNEY: "EMERGENCY REPAIRS, INCLUDING USE OF
ELECTRIC EEL MACHINE, ON STORMWATER DRAINS, INCLUDING
SECTIONAL REPLACEMENT, AT 86 DARLING POINT ROAD."
MANDATORY REQUIREMENT TO PREVENT FLOODING AND FOUNDATION
DAMAGE. COST: DOLS 424.10 (USOLS631.78) - VENDOR J. BAIN
& SONS P/L 58 RILEY STREET, SYDNEY.

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 CANBER 01881 290932Z

TM REQUEST URGENT CABLE ALLOTMENT OF EMERGENCY FUNDS
AMOUNTING TO US DOLS 2866.39 TO COVER ABOVE
UNANTICIPATED AND UNBUDGETED EXPENDITURES AT REFERENCED
CONSTITUENT POSTS.
GREEN

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 29 MAR 1974
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1974CANBER01881
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D740069-0264
From: CANBERRA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1974/newtext/t1974035/aaaaaece.tel
Line Count: 66
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION FBO
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Review Action: RELEASED, APPROVED
Review Authority: shawdg
Review Comment: n/a
Review Content Flags:
Review Date: 08 AUG 2002
Review Event:
Review Exemptions: n/a
Review History: RELEASED <08-Aug-2002 by elbezejf>; APPROVED <12 DEC 2002 by shawdg>
Review Markings:

Declassified/Released
US Department of State
EO Systematic Review
30 JUN 2005

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: EMERGENCY REPAIRS TO GOVERNMENT-HELD REALTY AT CONSTITUENT POSTS.
TAGS: ABLD, AS
To: STATE
Type: TE
Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005